

Annexure D**BUILDING SAFETY CERTIFICATE**No. 2871.Dated: 07.04.2026

It is certified that the existing building ...**Vidya Sanskar Academy**.....(name of the building or premises) at **Naidu Road, Phalavda, Meerut**.... (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2	NA	NA	NA	NA	NA

The building is owned/occupied by....**Vidya Sanskar Academy**...(name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Rural Engineering Services, Mawana Meerut (Name of Department/ Govt.) on 07.04.2026..... (date of inspection) in the presence of **Mr. Kuldeep Saini**, **Mawana, Meerut** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 07.04.2026.... for a period of 03.... years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 07.04.2026..... at Meerut..... by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.


सहायक अभियंता
ग्रामीण अभियंत्रण विभाग
प्रखण्ड - मेरठ

Signature with Seal:

Name: Vinod DubeDesignation: RES - Meerut

Name & Address of Department/ Office: _____